



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/10001BL0500/1

Work Order Type: Weatherization

Audit Name: 10001BL0500

CLIENT INFORMATION

Client Name:

Address:

Client ID: 10001BL0500

, 37801

Alt. Client ID: BLOUNT

AGENCY INFORMATION

Agency: Blount County Community Action Agency

Agency Phone: (865) 983-8411

Address: 3509 Tuckalee Pike
Maryville, TN 37803

Fax: (865) 681-1781

Email Address:

Agency Contact: Larson, Bruce

Work Phone: (865) 310-7333

Cell Phone: (865) 310-7333

Email Address: brujanie@charter.net

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Auditor: Bruce Larson
(865-310-7333)
Audit conducted on 4/3/2012
(8:20 A.M. - 10:10 A.M.)

Site Built: 1997

Client Name:

Client ID: 10001BL0500

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0500/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 8

Measures

Measure 1	Install (15" x 7") Vent cover to crawlspace vent (North Wall)	Components	Inspected						
Comment	Install (15" x 7") Vent cover to crawlspace vent (North Wall)		<input type="checkbox"/>						
		Estimated	Actual						
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total: <input type="text"/>		
Field Notes:									

Measure 2	Replace (3" x 12") piece of white soffit by porch (West Wall)	Components	Inspected						
Comment	Replace (3" x 12") piece of white soffit by porch (West Wall). Birds are getting into attic.		<input type="checkbox"/>						
		Estimated	Actual						
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total: <input type="text"/>		
Field Notes:									

Client Name:
Client ID: 10001BL0500
Alt. Client ID: BLOUNT

Work Order (Bid Form)
Work Order Name: WO/10001BL0500/1
Report Run On: 4/9/2012

DOE Weatherization Assistant
Version 8.6.0
Page 2 of 8

Measure 3 Replace Existing Duct Boot in Master Bath**Components****Inspected**

Comment This measure should be done only if new HVAC Unit is installed. Existing HVAC unit is INOPERABLE.

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
				<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
				<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:	<input type="text"/>	

Field Notes:**Measure 4 Infiltration Redctn****Components****Inspected****Comment**☐

1. Remove/Replace broken bottom pane in Window # 8. (27" x 21")
2. Remove/Replace existing attic access door. Opening is (38" x 22"). Use 1/2 " plywood. Weather strip and insulate top of door (R - 38) Add hardware.

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Su	Infiltration Reduction	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
				<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
				<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:	<input type="text"/>	

Field Notes:

Client Name:

Client ID: 10001BL0500

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0500/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 8

Measure 5 DWH Tank Insulation**Components****Inspected****Comment** 50 Gallon Electric☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 6 DWH Pipe Insulation****Components****Inspected****Comment**☐

Insulate a TOTAL of (36") of water pipes (Hot/Cold)

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 10001BL0500

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0500/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 8

Measure 7 Add 4' Guttering and 6' downspout to existing gutter on WW/NW Porch Corner**Components****Inspected****Comment** Add 4' Guttering and 6' downspout to existing gutter on WW/NW Porch Corner. 3" White.☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
				<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
				<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:**Measure 8 Add Downspouts (6') ea. To 3 existing gutterings. 3" size (white).****Components****Inspected****Comment** (3) existing gutters needs extensions of 6' downspouts. 3" in size. White. Total of 18 LN Ft.☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Client Name:

Client ID: 10001BL0500

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0500/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 5 of 8

Measure 9 Fix Not Operational Bathroom Exhaust Fan**Components****Inspected**

Comment Exhaust Fan in Master Bath has been disconnected.
Reconnect Exhaust fan.

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:**Measure 10 PressureRelief Piping Needed****Components****Inspected**

Comment Install Extension of 5' of Pressure Relief Piping thru floor to crawlspace.

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Pressure relief piping (+)	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Client Name:

Client ID: 10001BL0500

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0500/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 6 of 8

**Measure 11 Remove/Replace Broken Dryer Vent
Hose in Crawlspace (20') Add Hood to
East Wall**

Components

Inspected

Comment Remove/Replace Broken Dryer Vent Hose in Crawlspace (20') Add Hood to
East Wall

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

**Measure 12 Remove/Replace HVAC with 2 TON Heat
Pump.**

Components

Inspected

Comment Client has no Heat/Air. Existing Unit is INOPERABLE.
Remove/Replace existing INOPERABLE Heat Pump and replace with 2 TON
Heat Pump.

☐

Total Sq. ft of home: 1040.

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 10001BL0500

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0500/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 7 of 8

Measure 13 Repair approx. 25 ' of existing Flex Duct Components**Inspected**

Comment This measure should be done only if HVAC unit is replaced. Existing HVAC unit is INOPERABLE.

☐

There are various breaches in existing duct work. Needs to be retaped.
Approx. 25 '.

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 10001BL0500

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0500/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 8 of 8